FORM MR-AR (Revised 2/2001)

### STATE OF UTAH

## DEPARTMENT OF NATURAL RESOURCES

# **DIVISION OF OIL, GAS AND MINING** 1594 West North Temple - Suite 1210

Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940

#### ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	<u>Genera</u>	el Information
	1.	Report Time Period: From (mo./yr.) <u>Jan 2005</u> To (mo./yr.) <u>December 2005</u>
	2.	DOGM File Number (Mine No): M/043/014
	3.	Mine Name: Henefer Red Clay
	4.	Mineral(s) Mined (or permitted to mine):Clay
	5.	Type of mine:   ☐ Surface Mine or ☐ Underground Mine
	6.	Legal Description (Location of Lands Affected):
		N ½, SE ¼, 1/4, Section 33, Township 4N, Range 4E
		S ½, NE ¼, 1/4, Section 34, Township 4N, Range 4E
		<u>NE ¼, SE ¼, 1/4, Section 34</u> , Township 4N, Range 4E
	7.	Name of Operator or Company: <u>Interpace Industries, Inc</u>
	8.	Permanent Street Address: 736 W Harrisville Rd.
		City, State, Zip: Ogden, UT 84404
		Phone: (801) 782-7933 Fax: (801)782-5047
	9.	Company Representative (or designated operator):
		Name: Aaron Hancock
		Title: Plant Manager
		Business Address: P.O. Box 12118
		City, State, Zip: Ogden, UT 84412
		Phone: (801) 782-7933 Fax: (801)782-5047
		Please check if any of the above information has changed since previous year.
П.	Mining	and Reclamation
	1.	Was there any mine related activity during the past year? Yes ☒ No ☐
	2.	If no - what was the last year of activity?
	3.	If yes - how much ore or mineral was mined? <u>0 (zero) tons clay</u> <b>RECEIVED</b>
		JAN 2 7 2006

- Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
   Hauled 2,600 tons of clay from the stockpile pad.
- 5. How much additional acreage was disturbed during the past year? 0 (zero) acres
- 6. How much acreage was **reclaimed** during the past year? <u>0 (zero) acres</u>
- 7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

  None
- 8. What is the **total disturbed acreage of entire project** at years end? 12.65
- 9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
  Will mine approximately 20,000 tons of clay, Will haul approximately 8,000 tons of clay.

**NOTE**: Section III., "Additional Information" applies only to large mining operations.

#### III. Additional Information - R647-4-121.2 and .3

- 1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
- 2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

#### IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Aaron Hancock

Title of Operator: Plant Manager

Signature of Operator:

Date: January 25, 2006

jb

o:\forms\reports\MR-AR